


Headlamp Surface Oxidation - Top of Lens

Service Category Vehicle Exterior

Section Lighting (ext)

Market USA



Applicability

YEAR(S)	MODEL(S)	ADDITIONAL INFORMATION
2010 – 2012	4Runner	

Introduction

Some 2010 – 2012 model year 4Runner vehicles may exhibit a condition where the top, horizontal clear plastic surface of the headlamp appears to be oxidized or has a hazy appearance. Improved headlamp assemblies have been developed to address this condition.

Figure 1.



Production Change Information

This bulletin applies to vehicles produced **BEFORE** the Production Change Effective VINs shown below.

MODEL	DRIVETRAIN	DRIVE	PRODUCTION CHANGE EFFECTIVE VIN
4Runner	ZU5JR	2WD	JTEZU5JR#C5033625
	BU5JR	4WD	JTEBU5JR#C5077980

Headlamp Surface Oxidation - Top of Lens

Parts Information

PREVIOUS PART NUMBER	CURRENT PART NUMBER	PART NAME	QTY
81130-35530	Same	Headlamp, RH, Trail Package	1
81130-35520	Same	Headlamp, RH	1
81170-35530	Same	Headlamp, LH, Trail Package	1
81170-35520	Same	Headlamp, LH	1