


 : SPLICE POINTS

Code	See Page	Wire Harness with Splice Points	Code	See Page	Wire Harness with Splice Points
I1	40	Cowl Wire	I10	40	Cowl Wire
I5					


B16 (A)



D16




J4




(Hint : See Page 7)

J9




(Hint : See Page 7)

J10 (A)
BLACK




(Hint : See Page 7)

J11 (B)
BLACK




(Hint : See Page 7)


P4




P5




P6




P7 (A)



P8
BLACK



P9
BLACK



P10



P11



P26 (B)

