

4365 Austin Bluffs Pkwy
Colorado Springs, CO 80918
(719) 309-2266
abservice@adamautorepair.com



Plate CO BPN611
Description Black 1999 Toyota 4Runner SR5 V6 3.4L
3378CC VIN N
VIN JT3HN86R7X0224499
Odometer 246,775

Page 1 of 8

Sub \$0.00

Inspection

Maintenance Evaluation

Complete maintenance evaluation using our comprehensive digital vehicle health report.

Labor

\$58.96 *

Technician: Gabe Olipas

Sub \$58.96

Digital Inspection Result(s)

Inspection results from SmartFlow Digital Vehicle Inspections

-- Added by SmartFlow on 10/13/2021 --

Adam & Son Maintenance Evaluation, rev. 1

\$0.00 *

<https://motorist.autovitals.com//Fx8P6k>

Technician: Gabe Olipas

Sub \$0.00

Service

2005 CHEVROLET TRAILBLAZER LOANER - SILVER

LICENSE PLATE BRV734 / VIN 1GNDT13S152168079 / SILVER

Loaner

\$0.00 *

Technician: Gabe Olipas

Sub \$0.00

Windshield Wiper Blade

Remove and Replace components as required to access and install materials, and/or perform needed service. Retest and verify repair as required. Perform final road test where applicable.

-- Added by SmartFlow on 10/13/2021 --

Labor

\$0.00 *

Technician: Gabe Olipas

Wiper Blade

2 Unit

\$4.98 / Unit

\$9.95 *CS

Sub \$9.95

-- Inspection Results from AutoVitals SmartFlow --

For 'Wipers' the following conditions have been found: Front wipers streaking, Rear wiper streaking.

Notes:

Supporting Images and Videos:

For more info, check inspection results <https://motorist.autovitals.com//FxRskn>.

Brake Light Bulb

Remove and Replace components as required to access and install materials, and/or perform needed service. Retest and verify repair as required. Perform final road test where applicable.

-- Added by SmartFlow on 10/13/2021 --

Labor

\$0.00 *

Technician: Gabe Olipas

Multi Purpose Bulb

1 Unit

\$2.83 / Unit

\$2.83 *CS

Sub \$2.83

-- Inspection Results from AutoVitals SmartFlow --

For 'Lights' the following conditions have been found: Center high mount brake light inoperative.

Notes:

* Center high mount brake light is inoperative

Supporting Images and Videos:

For more info, check inspection results <https://motorist.autovitals.com//FxRskn>.

Manual Transmission Fluid Exchange

Remove existing fluid(s). Additional chemicals may be added to completely clean system contamination. Fill system fluid(s) to proper capacity with new fluid. Fluid additives and/or conditioners may be required. Leak test vehicle system. Perform final road test where applicable.

-- Added by SmartFlow on 10/13/2021 --

Labor

\$60.56 *

Technician: Gabe Olipas

BG Syncro Shift w/ MGC Additive

1 Unit

\$94.82 / Unit

\$94.82 *CS

BG Syncro Shift - Additional Fluid

2 Unit

\$36.73 / Unit

\$73.46 *CS

Sub \$228.84

-- Inspection Results from AutoVitals SmartFlow --
 For 'Transmission Fluid' the following conditions have been found: Manual Transmission, Dark.
 Notes:
 * Manual Transmission Fluid Exchange
 Supporting Images and Videos:
 * Image <https://motorist.autovitals.com/I/FxRsmo>
 For more info, check inspection results <https://motorist.autovitals.com/I/FxRskn>.

Brake Fluid System Service

Connect fluid service equipment to remove existing fluid. Additional cleaning chemicals may be added to assist in cleaning system contamination. Fill system fluid(s) to proper capacity with new fluid. Fluid additives and/or conditioner may be added to system. Leak test vehicle system. Perform final road test where applicable.

-- Added by SmartFlow on 10/13/2021 --

Perform Brake Fluid Service			\$131.62 *
Technician: Gabe Olipas			
BRAKE FLUID	1 Unit	\$18.22 / Unit	\$18.22 *CS
		Sub	\$149.84

-- Inspection Results from AutoVitals SmartFlow --
 For 'Brake Fluid' the following conditions have been found: Discolored.
 Notes:
 * Brake Fluid is contaminated and needing service.
 Supporting Images and Videos:
 For more info, check inspection results <https://motorist.autovitals.com/I/FxRskn>.

Radiator Coolant Hose - Upper

Remove and Replace components as required to access and install materials, and/or perform needed service. Additional fluids may be required to complete this service. Retest and verify repair as required. Perform final road test where applicable.

-- Added by SmartFlow on 10/13/2021 --

Remove & Replace Radiator Hose - Upper			\$117.86 *
Technician: Gabe Olipas			
Upper Radiator Or Coolant Hose	1 Unit	\$53.53 / Unit	\$53.53 *CS
Anti-Freeze Coolant	1 Unit	\$12.83 / Unit	\$12.83 *CS
		Sub	\$184.22

-- Inspection Results from AutoVitals SmartFlow --
 For 'Coolant Hoses' the following conditions have been found: Upper radiator hose leaking.
 Notes:
 * Upper radiator hose is leaking and needs replaced.
 Supporting Images and Videos:
 * Image <https://motorist.autovitals.com/I/FxRsnp>
 For more info, check inspection results <https://motorist.autovitals.com/I/FxRskn>.

Fuel Injection Cleaning Service

Connect fuel service equipment to fuel delivery system, add BG chemicals to clean system contamination. Add fluid additives and/or conditioner to complete system flush. Leak test vehicle system. Perform final road test where applicable.

-- Added by SmartFlow on 10/13/2021 --

Perform Fuel Injection Service			\$144.22 *
Technician: Gabe Olipas			
BG - Complete Fuel System Service Kit	1 Unit	\$79.07 / Unit	\$79.07 *CS
		Sub	\$223.29

-- Inspection Results from AutoVitals SmartFlow --
 For 'Throttle Body' the following conditions have been found: Dirty.
 Notes:
 * Recommend Fuel Injection Cleaning service
 Supporting Images and Videos:
 * Image <https://motorist.autovitals.com/I/FxRsoq>
 For more info, check inspection results <https://motorist.autovitals.com/I/FxRskn>.

Timing Belt Service w/ Water Pump

Remove and Replace components as required to access and install materials, and/or perform needed service. Additional fluids may be required to complete this service. Retest and verify repair as required. Perform final road test where applicable.

-- Added by SmartFlow on 10/13/2021 --

Remove & Replace Timing Belt			\$741.01 *
* Remove & Replace Camshaft Oil Seal			
* Remove & Replace Camshaft Oil Seal			
* Remove & Replace Crankshaft Oil Seal - Front			
* Remove & Replace Water Pump			
Technician: Gabe Olipas			

Timing Belt Kit With Water Pump	1 Unit	\$518.15 / Unit	\$518.15 *CS
Camshaft Seal	2 Unit	\$64.85 / Unit	\$129.70 *CS
Crankshaft Seal Kit	1 Unit	\$20.19 / Unit	\$20.19 *CS
Anti-Freeze Coolant	2 Unit	\$12.83 / Unit	\$25.66 *CS
Sub			\$1,434.71

-- Inspection Results from AutoVitals SmartFlow --

For 'Timing Belt' the following conditions have been found: Due by mileage, Other - See notes.

Notes:

* Found no timing belt replacement stickers in engine bay. Belt doesn't look to be cracking or excessively worn. Suggest based on mileage, please convene with guest to see if performed in recent history.

Supporting Images and Videos:

For more info, check inspection results <https://motorist.autovitals.com/I/FxRskn>.

Spark Plug

Remove and Replace components as required to access and install materials, and/or perform needed service. Retest and verify repair as required. Perform final road test where applicable.

-- Added by SmartFlow on 10/13/2021 --

Remove & Replace Spark Plugs			\$137.50 *
Technician: Gabe Olipas			
Resistor Spark Plug	6 Unit	\$23.71 / Unit	\$142.26 *CS
Sub			\$279.76

-- Inspection Results from AutoVitals SmartFlow --

For 'Spark Plug' the following conditions have been found: Excessive gap.

Notes:

* There is excessive gap in the spark plugs, Plugs and Wires need replaced.

Supporting Images and Videos:

* Image <https://motorist.autovitals.com/I/FxRspr>

* Image <https://motorist.autovitals.com/I/FxRsqi>

* Image <https://motorist.autovitals.com/I/FxRsrj>

For more info, check inspection results <https://motorist.autovitals.com/I/FxRskn>.

Spark Plug Wire Set

Remove and Replace components as required to access and install materials, and/or perform needed service. Retest and verify repair as required. Perform final road test where applicable.

-- Added by SmartFlow on 10/13/2021 --

Remove & Replace Spark Plug Wire Set			\$117.86 *
Technician: Gabe Olipas			
Tailored Resistor Ignition Wire Set	1 Unit	\$133.22 / Unit	\$133.22 *CS
Sub			\$251.08

-- Inspection Results from AutoVitals SmartFlow --

For 'Spark Plug' the following conditions have been found: Excessive gap.

Notes:

* There is excessive gap in the spark plugs, Plugs and Wires need replaced.

Supporting Images and Videos:

* Image <https://motorist.autovitals.com/I/FxRssk>

* Image <https://motorist.autovitals.com/I/FxRstm>

* Image <https://motorist.autovitals.com/I/FxRsun>

For more info, check inspection results <https://motorist.autovitals.com/I/FxRskn>.

Valve Cover Gasket

Remove and Replace components as required to access and install materials, and/or perform needed service, adjustments as required. Additional fluids may be required to complete this service. Retest and verify repair as required. Perform final road test where applicable.

-- Added by SmartFlow on 10/13/2021 --

Remove & Replace Valve Cover Gasket - Both			\$529.29 *
Technician: Gabe Olipas			
Valve Cover Gasket Set	1 Unit	\$136.15 / Unit	\$136.15 *CS
Plenum Gasket Set	1 Unit	\$87.45 / Unit	\$87.45 *CS
Sub			\$752.89

-- Inspection Results from AutoVitals SmartFlow --

For 'Under Hood Leaks' the following conditions have been found: Valve cover gasket leaking, Leak behind timing cover.

Notes:

* Valve Cover Gasket is leaking behind timing cover.

Supporting Images and Videos:

* Image <https://motorist.autovitals.com/I/FxRsvo>

* Image <https://motorist.autovitals.com/I/FxRswp>

* Image <https://motorist.autovitals.com/I/FxRsxq>

For more info, check inspection results <https://motorist.autovitals.com/I/FxRskn>.

Disc Brake Pads and Machine Rotors - Front

Remove and Replace front brake pads and machine rotors if applicable. Additional fluids may be required to complete this service. Re-test and verify repair as required. Perform final road test where applicable.

Labor			\$199.93 *
Technician: Gabe Olipas			
Front Ceramic Pads	1 Unit	\$59.93 / Unit	\$59.93 *CS
		Sub	\$259.86

Brake Flex Hose - Front

Remove and Replace components as required to access and install materials, and/or perform needed service, adjustments as required. Additional fluids may be required to complete this service. Retest and verify repair as required. Perform final road test where applicable.

-- Added by SmartFlow on 10/13/2021 --

Remove & Replace Brake Hose - One			\$117.86 *
Technician: Gabe Olipas			
Front Brake Hose	1 Unit	\$34.18 / Unit	\$34.18 *CS
		Sub	\$152.04

-- Inspection Results from AutoVitals SmartFlow --

For 'Front Brakes' the following conditions have been found: Left front hose damaged/leaking.

Notes:

* Found slight glaze on front rotors. Felt vibration in steering wheel during braking after brakes warmed up. Due to pad wear and life left, would suggest replacement of pads and hardware, machine rotors.

Supporting Images and Videos:

* Image <https://motorist.autovitals.com/I/FxRtDe>

* Image <https://motorist.autovitals.com/I/FxRtEf>

* Image <https://motorist.autovitals.com/I/FxRtFg>

* Image <https://motorist.autovitals.com/I/FxRtGh>

* Image <https://motorist.autovitals.com/I/FxRtHi>

* Image <https://motorist.autovitals.com/I/FxRtKj>

For more info, check inspection results <https://motorist.autovitals.com/I/FxRskn>.

Drum Brake Shoes, Drums & Hardware

Remove and Replace brake shoes, hardware and drums Clean and lubricate contact points. Additional fluids may be required to complete this service. Re-test and verify repair as required. Perform final road test where applicable.

-- Added by SmartFlow on 10/13/2021 --

Labor			\$155.83 *
Technician: Gabe Olipas			
Rear Premium Shoes	1 Unit	\$87.38 / Unit	\$87.38 *CS
Rear Drum Hardware Kit	1 Unit	\$32.86 / Unit	\$32.86 *CS
CTEK BRAKE DRUM	2 Unit	\$146.40 / Unit	\$292.80 *CS
		Sub	\$568.87

-- Inspection Results from AutoVitals SmartFlow --

For 'Rear Brakes' the following conditions have been found: Drums warped/out of round.

Notes:

* Recommend replacement of rear drums for remedy to body vibration during braking. Service pads and hardware as well. Adjust rear shoes after replacement, suspect cause of inoperative parking brake as well.

Supporting Images and Videos:

* Image <https://motorist.autovitals.com/I/FxRtLk>

* Image <https://motorist.autovitals.com/I/FxRtMc>

For more info, check inspection results <https://motorist.autovitals.com/I/FxRskn>.

Tire Rotation

Remove and Rotate 4 tires. Visual inspection of tire condition and tire wear pattern(s). Set tire pressure to proper inflation. Re-torque wheel lug nuts to manufacturers torque specifications. Perform final road test where applicable.

-- Added by SmartFlow on 10/13/2021 --

Labor			\$27.86 *
Technician: Gabe Olipas			

Please Note

Some wheels require lug nut re-torque. Ask your Service Consultant for details.
Keeping your tires properly inflated and rotated will assist in maximizing tire wear life and vehicle handling.

-- Inspection Results from AutoVitals SmartFlow --

For 'Left Front Tire' the following conditions have been found: Chopped.

Notes:

Supporting Images and Videos:

* Image <https://motorist.autovitals.com//FxFtNd>

For 'Right Front Tire' the following conditions have been found: Chopped.

Notes:

Supporting Images and Videos:

* Image <https://motorist.autovitals.com//FxFtPe>

For 'Left Rear Tire' the following conditions have been found: .

Notes:

Supporting Images and Videos:

* Image <https://motorist.autovitals.com//FxFtRf>

For 'Right Rear Tire' the following conditions have been found: .

Notes:

Supporting Images and Videos:

* Image <https://motorist.autovitals.com//FxFtSg>

For more info, check inspection results <https://motorist.autovitals.com//FxFtRskn>.

CV Axle Assembly - Left Front

Remove and Replace components as required to access and install materials, and/or perform needed service, adjustments as required. Additional fluids may be required to complete this service. Retest and verify repair as required. Perform final road test where applicable.

-- Added by SmartFlow on 10/13/2021 --

Remove & Install or Remove & Replace F Axle Shaft - One

\$255.36 *

Side

Technician: Gabe Olipas

New CV Shaft

1 Unit

\$179.40 / Unit

\$179.40 *CS

Sub \$434.76

-- Inspection Results from AutoVitals SmartFlow --

For 'CV Axles & Driveline' the following conditions have been found: 4WD/AWD, ABS, Left front CV axle boot torn, Other - See notes.

Notes:

* Verified guest concern of squeak when going forward and reverse. Suspect u-joint issue. Found no play in any of the u-joints. Suspect may need lubrication. Recommend greasing all u-joints and driveshafts.

Found left front inner cv boot has a hole. Has begun to fling grease inside wheel well. Recommend replacement of LF CV axle.

Supporting Images and Videos:

* Image <https://motorist.autovitals.com//FxFtTh>

* Image <https://motorist.autovitals.com//FxFtUi>

For more info, check inspection results <https://motorist.autovitals.com//FxFtRskn>.

Transfer Case Fluid Exchange

Drain and refill system fluid(s) to proper capacity with new fluid. Fluid additives and/or conditioners may be required. Leak test vehicle system. Perform final road test where applicable.

-- Added by SmartFlow on 10/13/2021 --

Perform Transfer Case Fluid Service

\$88.22 *

Technician: Gabe Olipas

BG Syncro Shift w/ MGC Additive

1 Unit

\$94.82 / Unit

\$94.82 *CS

Sub \$183.04

-- Inspection Results from AutoVitals SmartFlow --

For 'Transfer Case' the following conditions have been found: Fluid getting dark.

Notes:

* In picture, from top to bottom: front diff, t-case, rear diff.

Supporting Images and Videos:

For more info, check inspection results <https://motorist.autovitals.com//FxFtRskn>.

Rear Differential Service - 75W140

Remove and Replace components as required to access and install materials, and/or perform needed service, adjustments as required. Additional fluids may be required to complete this service. Retest and verify repair as required. Perform final road test where applicable.

Perform Differential Fluid Service			\$78.36 *
Technician: Gabe Olipas			
75W140 Syn Gear Oil	3 Unit	\$16.36 / Unit	\$49.08 *CS
BG Universal MGC	1 Unit	\$22.19 / Unit	\$22.19 *CS
		Sub	\$149.63

Power Steering Fluid Service

Connect flush equipment to remove existing fluid. Additional flush and cleaning chemicals may be added to assist in cleaning system contamination. Fill system fluid(s) to proper capacity with new fluid. Fluid additives and/or conditioners may be added to system. Leak test vehicle system. Perform final road test where applicable.

Perform Power Steering Fluid Service			\$88.22 *
Technician: Gabe Olipas			
BG Power Steering Cleaner & Conditioner	1 Unit	\$74.17 / Unit	\$74.17 *CS
		Sub	\$162.39

Power Steering Pump

Remove and Replace components as required to access and install materials, and/or perform needed service. Additional fluids may be required to complete this service. Retest and verify repair as required. Perform final road test where applicable.

Labor			\$0.00 *
Technician: Gabe Olipas			
Remanufactured Power Steering Pump With Reservoir	1 Unit	\$421.72 / Unit	\$421.72 *CS
Power Steering Pump Seal Kit	1 Unit	\$71.92 / Unit	\$71.92 *CS
		Sub	\$493.64

Alignment, Four Wheel

Inspect steering and suspension system components. Connect alignment equipment to verify and adjust front and rear wheel alignment settings for caster, camber, and toe in/out settings, thrust angle where applicable and center steering wheel. Some vehicles may require installation of alignment shims at additional charges. Adjust to meet manufacturers' specifications. Perform final road test where applicable.

Labor			\$119.96 *
Technician: Gabe Olipas			
Caster/Camber Adjusting Kit	2 Unit	\$110.83 / Unit	\$221.66 *CS
		Sub	\$341.62

Total Parts	\$3,431.04
Total Labor	\$3,956.20
Total Sublet	\$246.67
Total Before Taxes & Miscellaneous Charges	\$7,633.91

(*) Job Supplies		\$99.93 SC
(C) City Sales Tax	3.07 %	\$108.40
(S) State & County Sales Tax	5.13 %	\$181.14
Grand Total		\$8,023.38

I hereby authorize the above repair work to be done along with the necessary material and hereby grant you and/or your employees' permission to operate the vehicle described for testing and/or inspection. Express mechanic's lien is hereby acknowledged on above vehicle to secure the total amount of repairs thereto. A storage fee of \$10.00 per business day maybe applied after three days of notification that your vehicle repairs have been completed. TEARDOWN ESTIMATE: I understand that my vehicle will be reassembled within 3 days of the date shown above if I choose not to authorize the service recommended. All Parts removed will be discarded unless instructed otherwise:

Save all Parts _____. NOT RESPONSIBLE FOR LOSS OR DAMAGE TO CARS OR ARTICLES LEFT IN CARS IN CASE OF FIRE, THEFT OR ANY OTHER CAUSE.

Authorization(s)

10/11/2021 8:41 AM	\$65.34	Guest Concerns
		Maintenance Evaluation
		Authorized by Adkins, Adam

A handwritten signature in black ink, consisting of a series of connected loops and strokes, positioned above the text 'Authorization Signature'.

Authorization Signature